

INSPECTION REPORT


End of contract

GENERAL INFO

File	316052
License plate	2APX672
Vehicle identification number	VF3MRHNSMML031912
Dossier	2021 026 061
Make	Peugeot 5008 1.2PTech 96kW GT
Mileage	102818
First registration	07/06/2021
client availability date	24/06/2026
inspectionDate	26/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
113	Wing Rear Left // Painting	Y
134	Bumper Rear // Repair & Painting	Y
83	Door Front Left // Painting	N
104	Door Rear Left // Repair & Painting	N
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
18	Bumper Front / Spoiler / Replace	Y
31	Front Bonnet // Smart Repair Small	N
39	Engine Compartment / Silencer / Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
107	Door Rear Left / Trim / Replace	N
146	Back Side / Reflector L / Replace	Y
148	Back Side / Reflector R / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	N
202	Rocker Panel Right // Painting	Y
210	Door Front Right // Smart Repair Small	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
413	Seat Front Left / Rear Coating / Replace	Y
423	Seat Front Right / Rear Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y

Damage Pictures



Rocker Panel Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch




Side View Mirror Left / Direction Indicator / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Door Front Right // Smart Repair Small-dent



Door Rear Left / Trim / Replace-dent



Front Bonnet // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wheel Two Tone Rear Left // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front / Spoiler / Replace-Chemical reaction



Engine Compartment / Silencer / Replace-tear



Seat Front Left / Rear Coating / Replace-worn



Seat Front Right / Rear Coating / Replace-worn



Back Side / Reflector R / Replace-bad position



Back Side / Reflector L / Replace-bad position



Bumper Rear // Repair & Painting-scratch




Wing Rear Left // Painting-scratch



Door Rear Left // Repair & Painting-scratch + dent



Door Front Left // Painting-scratch



Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch