

INSPECTION REPORT





End of contract


GENERAL INFO

File	321363
License plate	2CEA555
Vehicle identification number	W1N2539111V370443
Dossier	2022 158 079
Make	Mercedes GLC 300de 4M
Mileage	40793
First registration	20/06/2022
client availability date	08/09/2026
inspectionDate	15/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	N
66	Wing Front Left // Polish	Y
104	Door Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
191	Door Rear Right // Smart Repair Medium	Y
211	Door Front Right // Smart Repair Medium	Y
282	Bumper Rear / Trim Center / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y


Damage Pictures



Door Front Right // Smart Repair Medium-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Front Left // Polish-scratch



Bumper Rear // Painting-scratch



Door Rear Left // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Rear / Trim Center / Replace-cracked