

INSPECTION REPORT





End of contract

GENERAL INFO

File	319966
License plate	2CAT373
Vehicle identification number	W1N2539111V371227
Dossier	2021 360 005
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	143737
First registration	13/05/2022
client availability date	11/08/2026
inspectionDate	21/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
63	Wing Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
191	Door Rear Right // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures




Door Rear Left // Polish-scratch




Wing Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch




Wing Front right // Polish-scratch



Door Front Right // Polish-scratch




Door Rear Right // Smart Repair Medium-scratch



Rocker Panel Left // Smart Repair Medium-dent



Bumper Front // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Front / Spoiler / Replace-cracked