

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                               |
|-------------------------------|-------------------------------|
| File                          | 319140                        |
| License plate                 | 2DRR738                       |
| Vehicle identification number | VR3FRHNSLPY558472             |
| Dossier                       | 2022 188 174                  |
| Make                          | Peugeot 308 SW 1.2 130 Active |
| Mileage                       | 80283                         |
| First registration            | 06/06/2023                    |
| client availability date      | 30/07/2026                    |
| inspectionDate                | 05/08/2026                    |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |






## DAMAGES

| Damages | Type                                                    | Acceptable |
|---------|---------------------------------------------------------|------------|
| 14      | Bumper Front // Repair & Painting                       | Y          |
| 63      | Wing Front Left // Painting                             | Y          |
| 80      | Door Front Left // Smart Repair Small                   | Y          |
| 93      | Rocker Panel Left // Repair & Painting                  | Y          |
| 100     | Door Rear Left // Smart Repair Small                    | Y          |
| 110     | Wing Rear Left // Smart Repair Small                    | Y          |
| 134     | Bumper Rear // Repair & Painting                        | Y          |
| 161     | Roof // Smart Repair Medium                             | Y          |
| 180     | Wing Rear Right // Smart Repair Small                   | Y          |
| 193     | Door Rear Right // Painting                             | Y          |
| 201     | Rocker Panel Right // Smart Repair Medium               | Y          |
| 233     | Wing Front right // Painting                            | Y          |
| 311     | Wheel Alloy Front Left // Repair                        | Y          |
| 321     | Wheel Alloy Rear Left // Repair                         | Y          |
| 341     | Wheel Alloy Front Right // Repair                       | Y          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace   | Y          |
| 624     | Front Right Door Interior Coating // Replace Completely | Y          |
| 860     | Interior Cleaning // Small                              | Y          |

## Damage Pictures



Door Front Left // Smart Repair Small-scratch



Wing Front Left // Painting-scratch




Wheel Alloy Rear Left // Repair-scratch




Wing Front right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch





Wing Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent




Door Rear Left // Smart Repair Small-dent



Bumper Rear // Repair & Painting-scratch + dent



Trunk Lid Interior Coating / Complete Panel / Replace-scratch + dent




Rocker Panel Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-bad repair






Door Rear Right // Painting-bad repair



Front Right Door Interior Coating // Replace Completely-tear





Interior Cleaning // Small-stain