

# INSPECTION REPORT




End of contract


## GENERAL INFO

File	309041
License plate	2AMV751
Vehicle identification number	VF3MRHNSMMS123131
Dossier	2021 035 162
Make	Peugeot 3008 1.2PTech 96kW All
Mileage	74501
First registration	18/05/2021
client availability date	01/04/2026
inspectionDate	09/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	N
101	Door Rear Left // Smart Repair Medium	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
860	Interior Cleaning // Small	N

## Damage Pictures



Damage within Renta-norm-



Rear Bonnet / Rear Window / Replace-scratch




Door Front Left // Smart Repair Small-scratch



Door Rear Left // Smart Repair Medium-dent



Roof // Polish-Chemical reaction



Interior Cleaning // Small-stain