

INSPECTION REPORT

End of contract


GENERAL INFO

File	317815
License plate	1YVA117
Vehicle identification number	W0VEFYHWCLJ531206
Dossier	2020324082
Make	Opel Comb.1.5D 55kW 2.0T L1H1
Mileage	93190
First registration	28/12/2020
client availability date	10/07/2026
inspectionDate	01/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
801	See External Expertise	N
891	Lettering Removal 15min	N
41	Windshield // Replace	N
64	Wing Front Left // Repair & Painting	N
83	Door Front Left // Painting	Y
114	Wing Rear Left // Repair & Painting	N
137	Bumper Rear // Replace without painting	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	N
244	Light / Front Right / Replace	N
294	Rear Loading Door Left // Repair & Painting	Y
304	Rear Loading Door Right // Repair & Painting	Y
540	Interior // Repair 1	N
618	Front Left Door Interior Coating / Door Handle / Replace	N
624	Front Right Door Interior Coating // Replace Completely	N
860	Interior Cleaning // Small	N

Damage Pictures




Bumper Rear // Replace without painting-scratch



Side View Mirror Right // Painting-scratch




Light / Front Right / Replace-scratch




Windshield // Replace-scratch




Front Right Door Interior Coating // Replace Completely-scratch




Door Front Left // Painting-scratch




Wing Front Left // Repair & Painting-dent





Rear Loading Door Right // Repair & Painting-dent



Door Front Right // Repair & Painting-dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Front Left Door Interior Coating / Door Handle / Replace-Incinerated



Interior // Repair 1-Incinerated



Interior Cleaning // Small-dirty



Door Rear Right // Repair & Painting-scratch





Wing Rear Right // Repair & Painting-scratch



Light / Rear Right / Replace-scratch



Lettering Removal 15min-



See External Expertise-