

INSPECTION REPORT




End of contract

GENERAL INFO

File	308896
License plate	2BNC331
Vehicle identification number	VF3MRHNSMMS258884
Dossier	2021112080
Make	Peugeot 5008 1.2PTech 96kW GT
Mileage	81469
First registration	20/01/2022
client availability date	25/03/2026
inspectionDate	31/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	Y
32	Front Bonnet // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	Y
113	Wing Rear Left // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
421	Seat Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y

Damage Pictures





Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Seat Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch




Front Bonnet // Painting-scratch



Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Seat Front Right // Repair-scratch



Door Rear Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front // Repair & Painting-scratch + dent





Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent




Door Front Right // Painting-bad repair




Door Rear Right // Painting-bad repair



Wing Rear Left // Painting-bad repair



Roof // Polish-Chemical reaction



Seat Front Left / Bottom Coating / Replace-worn