

INSPECTION REPORT


End of contract

GENERAL INFO

File	312421
License plate	2AAM247
Vehicle identification number	W0VEFYHYCLJ878693
Dossier	2020182035
Make	Opel Comb.1.5D 75kW 2.3T L2H1
Mileage	120847
First registration	01/02/2021
client availability date	07/05/2026
inspectionDate	20/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	








DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
84	Door Front Left // Repair & Painting	Y
106	Door Rear Left // Polish	Y
107	Door Rear Left / Trim / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
184	Wing Rear Right // Repair & Painting	N
205	Rocker Panel Right // Polish	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
272	Bumper Front / Trim Right / Replace	Y
294	Rear Loading Door Left // Repair & Painting	N
297	Rear Loading Door Left / Trim / Replace	N
411	Seat Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	N
569	Dashboard / Steering Wheel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures




Door Rear Left / Trim / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Right // Polish-scratch



Wing Front right // Polish-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Right / Replace-scratch




Bumper Front / Lower Cover Not Painted / Replace-scratch



Rocker Panel Right // Polish-scratch



Door Front Left // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent




Rear Loading Door Left / Trim / Replace-cracked



Front Right Door Interior Coating // Replace Completely-cracked




Interior // Repair 1-missing



Seat Front Left // Repair-missing



Interior Cleaning // Small-dirty



Dashboard / Steering Wheel / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn