

INSPECTION REPORT

End of contract

GENERAL INFO

File	311174
License plate	2BSG731
Vehicle identification number	ZFA2250006W19526
Dossier	2021337129
Make	Fiat Fiorino C.1.3Mjet 80 E6D
Mileage	121879
First registration	07/03/2022
client availability date	22/04/2026
inspectionDate	06/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	Y
40	Windshield // Repair	Y
54	Headlight / Front left / Replace	Y
64	Wing Front Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	Y
294	Rear Loading Door Left // Repair & Painting	N
304	Rear Loading Door Right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
412	Seat Front Left / Bottom Coating / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	N
541	Interior // Repair 2	N
554	Central Console // Replace Completely	Y
614	Front Left Door Interior Coating // Replace Completely	N

Damage Pictures



Trunk Compartment / Side Cover Left / Replace-scratch



Headlight / Front left / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch




Central Console // Replace Completely-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Wing Rear Right // Repair & Painting-dent



Roof // Smart Repair Medium-dent




Wing Rear Left // Repair & Painting-dent



Trunk Compartment / Side Cover Right / Replace-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent




Windshield // Repair-cracked




Interior // Repair 2-Incinerated



Front Left Door Interior Coating // Replace Completely-Incinerated



Interior // Repair 1-Incinerated



Seat Front Left / Bottom Coating / Replace-Incinerated



Wheel Front Left / Wheel Cover / Replace-missing