

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	308736
License plate	2AEH118
Vehicle identification number	W0V7D9EJ3L4466498
Dossier	2021 043 113
Make	Opel Crossland X 1.5D 88kW Edi
Mileage	125395
First registration	09/03/2021
client availability date	26/03/2026
inspectionDate	30/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
72	Side View Mirror Left // Painting	N
82	Door Front Left // Smart Repair Large	N
137	Bumper Rear // Replace without painting	N
159	Rear Bonnet / Rear Window / Replace	N
162	Roof // Painting	N
166	Roof / Antenna / Replace	N
196	Door Rear Right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N

## Damage Pictures






Damage within Renta-norm-




Door Front Left // Smart Repair Large-scratch + dent



Interior // Repair 1-Incinerated



Roof / Antenna / Replace-missing



Roof // Painting-Chemical reaction




Interior // Ionization Odor-bad smell



Door Rear Right // Polish-scratch



Side View Mirror Left // Painting-scratch



Rear Left Door Interior Coating // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Replace without painting-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Repair & Painting-scratch + dent



Door Front Right / Trim / Replace-scratch