

INSPECTION REPORT



End of contract

GENERAL INFO

File	314593
License plate	2ACK832
Vehicle identification number	VXEVFHKKMZ010904
Dossier	2020209073
Make	Opel Viv.TD 90kW 29 L3H1 Edit.
Mileage	76789
First registration	18/02/2021
client availability date	04/06/2026
inspectionDate	15/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	








DAMAGES

Damages	Type	Acceptable
223	Side View Mirror Right // Replace Not Painted	Y
226	Side View Mirror Right / Shell / Replace Painted	Y
14	Bumper Front // Repair & Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	N
64	Wing Front Left // Repair & Painting	N
77	Side View Mirror Left / Shell / Replace Not Painted	Y
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
114	Wing Rear Left // Repair & Painting	N
117	Wing Rear Left / Trim / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
162	Roof // Painting	N
174	Light / Rear Right / Replace	N
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
213	Door Front Right // Painting	Y
234	Wing Front right // Repair & Painting	N
293	Rear Loading Door Left // Painting	N
303	Rear Loading Door Right // Painting	N
412	Seat Front Left / Bottom Coating / Replace	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y

Damage Pictures



Door Front Right // Painting-scratch




Door Rear Right // Painting-scratch



Wing Front Left // Repair & Painting-dent



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Lower Cover Not Painted / Replace-scratch + dent




Wing Front right // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-cracked



Trunk Lid Interior Coating / MDF Rear Right / Replace-cracked



Trunk Lid Interior Coating / MDF Rear Left / Replace-cracked



Light / Rear Right / Replace-cracked




Seat Front Left / Bottom Coating / Replace-worn





Roof // Painting-Chipped paint




Wing Rear Right // Painting-scratch



Rear Loading Door Right // Painting-scratch



Rear Loading Door Left // Painting-scratch




Wing Rear Left / Trim / Replace-scratch



Door Front Left // Painting-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Side View Mirror Right // Replace Not Painted-scratch



Side View Mirror Right / Shell / Replace Painted-scratch