

INSPECTION REPORT

End of contract

GENERAL INFO

File	307187
License plate	2ASW159
Vehicle identification number	VR3FCYHZTMY510141
Dossier	2021 075 172
Make	Peugeot 508SW 1.5 BHDi Allure
Mileage	188240
First registration	05/07/2021
client availability date	03/03/2026
inspectionDate	24/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
73	Side View Mirror Left // Replace Not Painted	N
14	Bumper Front // Repair & Painting	Y
54	Headlight / Front left / Replace	N
84	Door Front Left // Repair & Painting	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
131	Bumper Rear // Smart Repair Medium	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	Y
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
194	Door Rear Right // Repair & Painting	Y
203	Rocker Panel Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	N
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
680	Keys Detachable Towing Hook //	N
860	Interior Cleaning // Small	N

Damage Pictures




Damage within Renta-norm-



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch





Wing Front right // Polish-scratch




Wheel Two Tone Rear Right // Repair-scratch



Roof // Polish-scratch



Door Rear Right // Repair & Painting-dent



Door Front Left // Repair & Painting-dent




Door Front Right // Repair & Painting-scratch + dent




Bumper Front // Repair & Painting-scratch + dent




Rocker Panel Right // Repair & Painting-scratch + dent




Rear Bonnet // Painting-bad repair



Bumper Rear / Lower Cover Not Painted / Replace-bad repair



Wing Rear Left // Painting-bad repair



Door Rear Left // Painting-bad repair



Wing Rear Right // Painting-bad repair




Headlight / Front left / Replace-cracked



Interior Cleaning // Small-stain



Trunk Compartment / Side Cover Left / Replace-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Trunk Compartment / Side Cover Right / Replace-scratch



Bumper Rear // Smart Repair Medium-scratch



Wheel Two Tone Rear Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Side View Mirror Left // Replace Not Painted-scratch