

INSPECTION REPORT



End of contract

GENERAL INFO

File	320364
License plate	2AGQ166
Vehicle identification number	VF3LCYHZJMS081470
Dossier	2020349053
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	153798
First registration	29/03/2021
client availability date	17/08/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
27	Front / Logo / Replace	N
32	Front Bonnet // Painting	N
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	N
100	Door Rear Left // Smart Repair Small	N
110	Wing Rear Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
153	Rear Bonnet // Painting	Y
163	Roof // Repair & Painting	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	N
180	Wing Rear Right // Smart Repair Small	N
222	Side View Mirror Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
233	Wing Front right // Painting	Y
244	Light / Front Right / Replace	N
273	Bumper Front / Grid Left / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
540	Interior // Repair 1	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Light / Rear Right / Replace-scratch



Bumper Front / Grid Left / Replace-scratch



Bumper Rear // Polish-scratch



Rear Bonnet // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wheel Alloy Rear Left // Repair-scratch



Dashboard / Steering Wheel / Replace-scratch



Side View Mirror Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch




Wheel Alloy Rear Right // Repair-scratch



Interior // Repair 1-dent



Wing Rear Left // Smart Repair Small-dent




Door Rear Left // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent



Door Front Left // Repair & Painting-dent



Roof // Repair & Painting-scratch + dent



Front Bonnet // Painting-bad repair



Light / Rear Right On Rear Bonnet / Replace-cracked



Front / Logo / Replace-missing



Seat Front Left / Bottom Coating / Replace-hole



Light / Front Right / Replace-Splashes



Lettering Removal 15min-