

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	309084
License plate	2BEQ176
Vehicle identification number	KMHC851CGNU266846
Dossier	2021 161 089
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	127373
First registration	22/10/2021
client availability date	27/03/2026
inspectionDate	02/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
104	Door Rear Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	Y
86	Door Front Left // Polish	Y
87	Door Front Left / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
131	Bumper Rear // Smart Repair Medium	N
161	Roof // Smart Repair Medium	N
169	Rear Bonnet / Spoiler / Replace & Painting	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
234	Wing Front right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
624	Front Right Door Interior Coating // Replace Completely	Y
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N


## Damage Pictures



See External Expertise-



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent




Side View Mirror Right / Shell / Replace Not Painted-cracked



Windshield // Replace-cracked



Door Front Left / Trim / Replace-Chemical reaction



Interior Cleaning // Small-stain



Bumper Rear // Smart Repair Medium-scratch




Light / Rear Right / Replace-scratch





Rear Bonnet / Spoiler / Replace & Painting-scratch



Roof // Smart Repair Medium-scratch



Wheel Alloy Rear Right // Repair-scratch




Wing Rear Right // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Repair-scratch




Dashboard / Steering Wheel / Replace-scratch




Wing Front right // Repair & Painting-scratch + dent






Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent





Wing Rear Left // Repair & Painting-scratch + dent