

INSPECTION REPORT





End of contract


GENERAL INFO

File	319815
License plate	2CCB326
Vehicle identification number	VSSZZZ5FZN6539313
Dossier	2021 282 001
Make	Seat Ateca 1.5TSI 150 Move DSG
Mileage	75277
First registration	31/05/2022
client availability date	28/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
13	Bumper Front // Painting	Y
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	N
110	Wing Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
139	Bumper Rear / Spoiler / Replace	Y
150	Rear Bonnet // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
225	Side View Mirror Right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
881	Key Price Range 1 //	N

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch




Bumper Front // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Right // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Roof // Smart Repair Medium-dent



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-dent




Wing Rear Left // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Painting-bad repair



Wing Rear Right // Painting-bad repair




Bumper Rear // Painting-bad repair





Windshield // Repair-cracked



Key Price Range 1 //-missing





See External Expertise-Splashes