

INSPECTION REPORT



End of contract

GENERAL INFO

File	319594
License plate	2AUF746
Vehicle identification number	VF3MCYHZUMS139539
Dossier	2021 187 101
Make	Peugeot 3008 1.5BHDi 96kW Allu
Mileage	114445
First registration	20/07/2021
client availability date	11/08/2026
inspectionDate	19/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-Chemical reaction



Wheel Two Tone Rear Left // Repair-Chemical reaction



Wheel Two Tone Front Left // Repair-Chemical reaction



Front Bonnet / Insulation / Replace-tear



Windshield // Repair-stone chipping