

INSPECTION REPORT


End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 309839 |
| License plate | 2DVK334 |
| Vehicle identification number | W1K2060541R048652 |
| Dossier | 2023 166 208 |
| Make | Mercedes C 300e 230kW Luxury L |
| Mileage | 25499 |
| First registration | 05/07/2023 |
| client availability date | 07/04/2026 |
| inspectionDate | 13/05/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | Y | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|---|------------|
| 14 | Bumper Front // Repair & Painting | N |
| 35 | Front Bonnet // Polish | Y |
| 78 | Side View Mirror Left / Direction Indicator / Replace | N |
| 110 | Wing Rear Left // Smart Repair Small | Y |
| 134 | Bumper Rear // Repair & Painting | N |
| 310 | Wheel Two Tone Front Left // Repair | N |
| 330 | Wheel Two Tone Rear Right // Repair | N |
| 340 | Wheel Two Tone Front Right // Repair | N |

Damage Pictures



Front Bonnet // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Left // Smart Repair Small-dent



Bumper Front // Repair & Painting-scratch + dent





Bumper Rear // Repair & Painting-scratch + dent