

INSPECTION REPORT


End of contract


GENERAL INFO

File	321069
License plate	2AJH228
Vehicle identification number	TMBJN7NPXM7019799
Dossier	2021 074 093
Make	Skoda Sup.Comb.TSI 150 Amb.DSG
Mileage	102850
First registration	14/04/2021
client availability date	28/08/2026
inspectionDate	07/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
15	Bumper Front // Replace & Painting	N
35	Front Bonnet // Polish	Y
41	Windshield // Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	N
201	Rocker Panel Right // Smart Repair Medium	N
432	Seat Rear Left / Bottom Coating / Replace	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
539	Trunk Compartment / Back Coating / Replace	Y
541	Interior // Repair 2	N
541	Interior // Repair 2	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Painting-scratch





Trunk Compartment / Back Coating / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch






Rocker Panel Right // Smart Repair Medium-dent



Door Rear Left // Smart Repair Small-dent



Bumper Front // Replace & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Left // Painting-bad repair



Windshield // Replace-cracked



Interior // Repair 2-Incinerated




Interior // Repair 2-N comf / out of order



Seat Rear Left / Bottom Coating / Replace-Incinerated



Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Small-dirty



Dashboard / Steering Wheel / Replace-worn



Lettering Removal 15min-