

INSPECTION REPORT


End of contract

GENERAL INFO

File	308619
License plate	1XSU617
Vehicle identification number	W1K2052001G013661
Dossier	2020015024
Make	Mercedes C Break 180d 90kW Aut
Mileage	105225
First registration	08/05/2020
client availability date	02/04/2026
inspectionDate	08/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
66	Wing Front Left // Polish	Y
124	Light / Rear left / Replace	Y
130	Bumper Rear // Smart Repair Small	N
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
174	Light / Rear Right / Replace	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures





Damage within Renta-norm-



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Wing Front Left // Polish-scratch



Rear Left Door Interior Coating // Repair-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Rear // Painting-scratch



Bumper Front // Painting-scratch + dent



Seat Front Left / Bottom Coating / Replace-tear



Interior Cleaning // Small-stain



Bumper Rear // Smart Repair Small-bad position