

INSPECTION REPORT


End of contract

GENERAL INFO

File	321282
License plate	PR9020
Vehicle identification number	VF3MCYHZUNS151455
Dossier	2022133003
Make	Peugeot 5008 1.5Hdi 130 GT Pac
Mileage	162719
First registration	21/11/2022
client availability date	01/09/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
117	Wing Rear Left / Trim / Replace	N
132	Bumper Rear // Smart Repair Large	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
11	Bumper Front // Smart Repair Medium	N
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	Y
41	Windshield // Replace	N
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	Y
113	Wing Rear Left // Painting	Y
162	Roof // Painting	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	Y
213	Door Front Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
310	Wheel Two Tone Front Left // Repair	N
411	Seat Front Left // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
421	Seat Front Right // Repair	Y
423	Seat Front Right / Rear Coating / Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures




Side View Mirror Right / Direction Indicator / Replace-scratch



Door Front Right // Painting-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Door Front Left // Painting-scratch




Wheel Two Tone Front Left // Repair-scratch



Wing Rear Left // Painting-scratch



Seat Front Left // Repair-scratch



Seat Front Right // Repair-scratch



Door Rear Right // Repair & Painting-dent



Door Rear Left // Repair & Painting-dent



Wing Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front / Spoiler / Replace-cracked




Interior // Repair 1-Incinerated



Windshield // Replace-glass damage




Trunk Compartment / Boot Cover / Replace-missing




Roof // Painting-Chemical reaction



Seat Front Right / Rear Coating / Replace-tear



Seat Front Left / Bottom Coating / Replace-worn



Front Bonnet // Painting-stone chipping



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Smart Repair Large-scratch



Wing Rear Left / Trim / Replace-scratch



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Smart Repair Medium-scratch