

# INSPECTION REPORT



End of contract


## GENERAL INFO

File	311301
License plate	2BJY679
Vehicle identification number	W1K1770101N268422
Dossier	2021 046 109
Make	Mercedes A 180 d Bus.Sol.Aut.
Mileage	30015
First registration	14/12/2021
client availability date	04/05/2026
inspectionDate	07/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
272	Bumper Front / Trim Right / Replace	N
274	Bumper Front / Grid Central / Replace	Y

## Damage Pictures



Damage within Renta-norm-



Bumper Front / Grid Central / Replace-cracked



Bumper Front // Replace & Painting-scratch + dent



Bumper Front / Trim Right / Replace-cracked