

INSPECTION REPORT


End of contract

GENERAL INFO

File	312334
License plate	2BRG344
Vehicle identification number	W1N2539111V326163
Dossier	2021069024
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	84254
First registration	23/02/2022
client availability date	07/05/2026
inspectionDate	26/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	Y
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
772	Interior / A Pillar Upper Cover / Replace	N
773	Interior / A Pillar Lower Cover / Replace	N

Damage Pictures



Rocker Panel Left // Smart Repair Medium-scratch + dent



Interior / A Pillar Lower Cover / Replace-tear



Interior / A Pillar Upper Cover / Replace-tear



Dashboard / Steering Wheel / Replace-worn



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Smart Repair Small-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Right // Repair-scratch



Seat Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Spoiler / Replace-cracked



Bumper Rear // Repair & Painting-scratch + dent