

INSPECTION REPORT


End of contract

GENERAL INFO

File	308832
License plate	2BRQ377
Vehicle identification number	W0VEFYHT2MJ956810
Dossier	2021154068
Make	Opel Comb.1.5D 55kW 2.0T L1H1
Mileage	197073
First registration	25/02/2022
client availability date	23/03/2026
inspectionDate	02/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
73	Side View Mirror Left // Replace Not Painted	N
80	Door Front Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
197	Door Rear Right / Trim / Replace	N
213	Door Front Right // Painting	Y
217	Door Front Right / Trim / Replace	Y
223	Side View Mirror Right // Replace Not Painted	N
227	Side View Mirror Right / Shell / Replace Not Painted	Y
293	Rear Loading Door Left // Painting	Y
304	Rear Loading Door Right // Repair & Painting	Y
324	Wheel Rear Left / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
412	Seat Front Left / Bottom Coating / Replace	Y
418	Seat Front Left / Armrest / Replace	N
540	Interior // Repair 1	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures





Rear Loading Door Left // Painting-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch





Bumper Front // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch




Side View Mirror Right / Shell / Replace Not Painted-scratch



Door Front Right // Painting-scratch



Door Front Right / Trim / Replace-scratch




Wing Rear Left // Smart Repair Small-dent




Door Front Left // Smart Repair Small-dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Seat Front Left / Armrest / Replace-cracked



Interior // Repair 1-Incinerated



Door Rear Right / Trim / Replace-missing



Wheel Front Right / Wheel Cover / Replace-missing



Wheel Rear Left / Wheel Cover / Replace-missing



Interior Cleaning // Small-dirty



Seat Front Left / Bottom Coating / Replace-worn



Side View Mirror Right // Replace Not Painted-hole



Side View Mirror Left // Replace Not Painted-hole