

INSPECTION REPORT



End of contract

GENERAL INFO

File	309094
License plate	2BDW509
Vehicle identification number	VR3USHNKKMJ828774
Dossier	2021 103 009
Make	Peugeot 2008 1.2 74kW Allure P
Mileage	90091
First registration	15/10/2021
client availability date	25/03/2026
inspectionDate	31/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	N
81	Door Front Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	N
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
213	Door Front Right // Painting	Y
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
413	Seat Front Left / Rear Coating / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
549	Interior / Headliner/ Replace	N
560	Interior / A Pillar Cover / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch




Bumper Rear / Spoiler / Replace-scratch




Bumper Rear // Painting-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch




Wing Rear Right / Trim / Replace-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Door Rear Right // Repair & Painting-scratch + dent



Interior / A Pillar Cover / Replace-Incinerated



Interior / Headliner/ Replace-Incinerated




Seat Front Left / Bottom Coating / Replace-Incinerated



Interior // Repair 1-Incinerated



Front Left Door Interior Coating // Replace Completely-Incinerated



Trunk Compartment / Boot Cover / Replace-missing



Front Bonnet // Painting-Chemical reaction



Wing Rear Right // Polish-Chemical reaction



Seat Front Left / Rear Coating / Replace-worn