

INSPECTION REPORT



End of contract

GENERAL INFO

File	306857
License plate	1XHY632
Vehicle identification number	W1V4156031U280416
Dossier	2019331174
Make	Mercedes Citan 109CDI L2 Perf.
Mileage	125054
First registration	10/01/2020
client availability date	27/02/2026
inspectionDate	10/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	N
44	Windshield / Trim / Replace	N
137	Bumper Rear // Replace without painting	N
163	Roof // Repair & Painting	N
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	N
304	Rear Loading Door Right // Repair & Painting	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N
644	Rear Right Door Interior Coating // Replace Completely	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures






Damage within Renta-norm-scratch







Wheel Alloy Rear Right // Repair-scratch




Light / Rear Right / Replace-scratch




Door Rear Right // Repair & Painting-dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Roof // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Rear Right Door Interior Coating // Replace Completely-cracked



Trunk Lid Interior Coating / MDF Rear Right / Replace-cracked



Bumper Rear // Replace without painting-cracked



Interior Cleaning // Small-stain



Windshield / Trim / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch