

INSPECTION REPORT




End of contract


GENERAL INFO

File	320806
License plate	2BRZ973
Vehicle identification number	W1N2539111G057835
Dossier	2021217006
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	211550
First registration	02/03/2022
client availability date	24/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
125	Light / Rear Left On Rear Bonnet / Replace	N
133	Bumper Rear // Painting	N
180	Wing Rear Right // Smart Repair Small	N
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	N


Damage Pictures



Light / Rear Left On Rear Bonnet / Replace-scratch



Bumper Rear // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Rear Left // Polish-scratch




Door Front Left // Smart Repair Medium-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch




Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-scratch + dent



Interior // Repair 1-cracked



Seat Front Left / Bottom Coating / Replace-worn