

INSPECTION REPORT

End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 300284 |
| License plate | 1YMX170 |
| Vehicle identification number | W0VBE8E55L8009632 |
| Dossier | 1249 668 297 |
| Make | Opel Astra ST 1.2 96kW Eleganc |
| Mileage | 62774 |
| First registration | 30/01/2020 |
| client availability date | 12/12/2025 |
| inspectionDate | 18/12/2025 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | N | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|-----------------------------------|------------|
| 311 | Wheel Alloy Front Left // Repair | N |
| 331 | Wheel Alloy Rear Right // Repair | N |
| 341 | Wheel Alloy Front Right // Repair | N |
| 346 | Tyre Front Right // Replace | N |
| 411 | Seat Front Left // Repair | Y |
| 540 | Interior // Repair 1 | N |
| 543 | Interior // Ionization Odor | N |
| 549 | Interior / Headliner/ Replace | N |

Damage Pictures



Damage within Renta-norm-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Seat Front Left // Repair-scratch



Interior / Headliner/ Replace-Incinerated



Interior // Repair 1-Incinerated



Tyre Front Right // Replace-tear