

INSPECTION REPORT






End of contract

GENERAL INFO

File	318948
License plate	2BMM258
Vehicle identification number	W1K1770101V120969
Dossier	2021088022
Make	Mercedes A 180 d Bus.Sol.Essen
Mileage	239031
First registration	14/01/2022
client availability date	06/08/2026
inspectionDate	07/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
83	Door Front Left // Painting	Y
134	Bumper Rear // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N


Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch




Bumper Front // Painting-scratch



Rocker Panel Right // Smart Repair Medium-dent




Bumper Rear // Repair & Painting-scratch + dent




Windshield // Repair-cracked



Wheel Two Tone Front Right // Repair-Chemical reaction



Wheel Two Tone Front Left // Repair-Chemical reaction



Interior Cleaning // Small-stain



Door Front Left // Painting-Chipped paint