

INSPECTION REPORT

End of contract

GENERAL INFO

File	312224
License plate	AV4868
Vehicle identification number	W1K1770101N284211
Dossier	2022003002
Make	Mercedes A 180 d 116 Bus.Solut
Mileage	152519
First registration	23/05/2022
client availability date	06/05/2026
inspectionDate	08/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	



DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	Y
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	N
70	Wing Front Left / Inner Fender / Replace	N
104	Door Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	Y
131	Bumper Rear // Smart Repair Medium	N
161	Roof // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
222	Side View Mirror Right // Painting	N
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
413	Seat Front Left / Rear Coating / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures




Light / Rear left / Replace-scratch



Wing Rear Right // Polish-scratch



Door Rear Right / Trim / Replace-scratch



Side View Mirror Right // Painting-scratch




Wing Front right // Polish-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Roof // Smart Repair Medium-dent



Door Front Right // Repair & Painting-dent



Rocker Panel Right // Smart Repair Medium-dent




Door Rear Left // Repair & Painting-dent




Door Rear Right // Repair & Painting-scratch + dent




Bumper Rear // Smart Repair Medium-bad repair



Windshield // Replace-glass damage



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Front Bonnet // Painting-stone chipping



Wing Front Left / Inner Fender / Replace-bad position



Seat Front Left / Rear Coating / Replace-bad position