

INSPECTION REPORT



End of contract

GENERAL INFO

File	308616
License plate	2AFA901
Vehicle identification number	W1N2539141V290325
Dossier	2020078073
Make	Mercedes GLC 220d
Mileage	207126
First registration	15/03/2021
client availability date	31/03/2026
inspectionDate	10/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
31	Front Bonnet // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
154	Rear Bonnet // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
272	Bumper Front / Trim Right / Replace	Y
310	Wheel Two Tone Front Left // Repair	N

Damage Pictures



Damage within Renta-norm-



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Polish-scratch



Bumper Front / Trim Right / Replace-scratch



Door Front Right // Polish-scratch



Bumper Rear // Polish-scratch



Front Bonnet // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent