

INSPECTION REPORT


End of contract

GENERAL INFO

File	314040
License plate	QY5134
Vehicle identification number	WDF44760313669252
Dossier	2022088053
Make	Mercedes eVito MWB 35kWh 116 L
Mileage	59916
First registration	15/04/2022
client availability date	29/05/2026
inspectionDate	02/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
186	Wing Rear Right // Polish	N
194	Door Rear Right // Repair & Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
31	Front Bonnet // Smart Repair Small	N
77	Side View Mirror Left / Shell / Replace Not Painted	Y
84	Door Front Left // Repair & Painting	N
92	Rocker Panel Left // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
210	Door Front Right // Smart Repair Small	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
291	Rear Loading Door Left // Smart Repair Medium	Y
301	Rear Loading Door Right // Smart Repair Medium	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
561	Dashboard // Repair	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N
611	Front Left Door Interior Coating // Repair	N
621	Front Right Door Interior Coating // Repair	N
684	Charger Cable //	N
860	Interior Cleaning // Small	Y
883	Key Price Range 2 //	N

Damage Pictures



Rear Loading Door Right // Smart Repair Medium-scratch
+ dent



Door Front Left // Repair & Painting-scratch + dent



Trunk Lid Interior Coating / MDF Rear Right / Replace-cracked



Roof // Polish-Chemical reaction



Interior Cleaning // Small-stain




Key Price Range 2 //-worn




Dashboard // Repair-scratch



Light / Rear Right / Replace-scratch



Front Right Door Interior Coating // Repair-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch






Bumper Front / Lower Cover Not Painted / Replace-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Rocker Panel Left // Painting-scratch



Front Left Door Interior Coating // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-dent



Front Bonnet // Smart Repair Small-dent



Door Front Right // Smart Repair Small-dent






Rear Loading Door Left // Smart Repair Medium-dent






Trunk Compartment / Side Cover Left / Replace-scratch + dent



Trunk Compartment / Side Cover Right / Replace-scratch
+ dent



Wing Rear Right // Polish-scratch



Door Rear Right // Repair & Painting-scratch + dent