

INSPECTION REPORT


End of contract

GENERAL INFO

File	306819
License plate	1XHY386
Vehicle identification number	W1V4156031U280410
Dossier	2019331170
Make	Mercedes Citan 109CDI L2 Perf.
Mileage	100182
First registration	10/01/2020
client availability date	27/02/2026
inspectionDate	09/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




DAMAGES

Damages	Type	Acceptable
17	Bumper Front // Replace without painting	N
33	Front Bonnet // Repair & Painting	N
40	Windshield // Repair	Y
163	Roof // Repair & Painting	N
166	Roof / Antenna / Replace	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
244	Light / Front Right / Replace	Y
311	Wheel Alloy Front Left // Repair	N
336	Tyre Rear Right // Replace	N
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
883	Key Price Range 2 //	N

Damage Pictures





Damage within Renta-norm-scratch




Roof // Repair & Painting-dent



Bumper Front // Replace without painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Side View Mirror Right / Shell / Replace Not Painted-cracked



Roof / Antenna / Replace-cracked



Windshield // Repair-glass damage



Seat Front Left / Bottom Coating / Replace-tear



Tyre Rear Right // Replace-tear



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Light / Front Right / Replace-scratch