

INSPECTION REPORT


End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 312649 |
| License plate | 1XME338 |
| Vehicle identification number | VXEVFHKKLZ021694 |
| Dossier | 2019267247 |
| Make | Opel Viv.TD 90kW 31 L3H1 Edit. |
| Mileage | 143168 |
| First registration | 10/02/2020 |
| client availability date | 11/05/2026 |
| inspectionDate | 08/06/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | Y | |
| Towbar (+keys) | | Y | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | N | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |






DAMAGES

| Damages | Type | Acceptable |
|---------|--|------------|
| 64 | Wing Front Left // Repair & Painting | N |
| 87 | Door Front Left / Trim / Replace | N |
| 93 | Rocker Panel Left // Repair & Painting | N |
| 203 | Rocker Panel Right // Repair & Painting | N |
| 234 | Wing Front right // Repair & Painting | N |
| 12 | Bumper Front // Smart Repair Large | N |
| 13 | Bumper Front // Painting | Y |
| 81 | Door Front Left // Smart Repair Medium | N |
| 104 | Door Rear Left // Repair & Painting | N |
| 114 | Wing Rear Left // Repair & Painting | N |
| 137 | Bumper Rear // Replace without painting | N |
| 184 | Wing Rear Right // Repair & Painting | N |
| 196 | Door Rear Right // Polish | Y |
| 214 | Door Front Right // Repair & Painting | N |
| 217 | Door Front Right / Trim / Replace | Y |
| 244 | Light / Front Right / Replace | Y |
| 293 | Rear Loading Door Left // Painting | N |
| 306 | Rear Loading Door Right / Polish | Y |
| 534 | Trunk Compartment / Carpet / Replace | Y |
| 569 | Dashboard / Steering Wheel / Replace | Y |
| 592 | Trunk Lid Interior Coating / MDF Rear Left / Replace | Y |
| 860 | Interior Cleaning // Small | Y |


Damage Pictures



Wing Rear Left // Repair & Painting-dent




Door Rear Left // Repair & Painting-dent



Rear Loading Door Right / Polish-scratch



Bumper Rear // Replace without painting-scratch



Door Front Left // Smart Repair Medium-scratch



Light / Front Right / Replace-scratch




Bumper Front // Smart Repair Large-scratch



Bumper Front // Painting-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Trunk Compartment / Carpet / Replace-cracked



Rear Loading Door Left // Painting-rust



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Trunk Lid Interior Coating / MDF Rear Left / Replace-hole




Door Front Right // Repair & Painting-scratch + dent




Door Front Left / Trim / Replace-scratch



Rocker Panel Left // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-dent