

INSPECTION REPORT


End of contract

GENERAL INFO

File	308747
License plate	1YNA550
Vehicle identification number	VR3UDYHZRLJ867226
Dossier	2020030036
Make	Peugeot 2008 1.5BlueHDi 96kW G
Mileage	134310
First registration	23/10/2020
client availability date	03/04/2026
inspectionDate	10/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
38	Front Bonnet / Insulation / Replace	N
72	Side View Mirror Left // Painting	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
139	Bumper Rear / Spoiler / Replace	Y
156	Rear Bonnet // Polish	Y
162	Roof // Painting	Y
193	Door Rear Right // Painting	Y
222	Side View Mirror Right // Painting	N
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
641	Rear Right Door Interior Coating // Repair	N
840	Interior Cleaning // Large	N

Damage Pictures



Bumper Front // Painting-scratch



Roof // Painting-scratch



Side View Mirror Right // Painting-scratch



Seat Front Right // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Rear Bonnet // Polish-scratch



Seat Front Left // Repair-scratch



Door Front Left / Trim / Replace-scratch




Side View Mirror Left // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent




Front Bonnet / Insulation / Replace-cracked



Wheel Two Tone Front Left // Repair-Chemical reaction





Interior Cleaning // Large-stain