

INSPECTION REPORT







End of contract

GENERAL INFO

File	318814
License plate	2CEH869
Vehicle identification number	W1N2539111V390350
Dossier	2021 330 114
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	148795
First registration	22/06/2022
client availability date	27/07/2026
inspectionDate	07/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
151	Rear Bonnet // Smart Repair Medium	Y
159	Rear Bonnet / Rear Window / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
421	Seat Front Right // Repair	N
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Door Rear Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Smart Repair Medium-scratch



Seat Front Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Smart Repair Medium-scratch



Rear Bonnet / Rear Window / Replace-scratch



Interior // Repair 1-scratch



Door Rear Right // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent



Wing Rear Left // Repair & Painting-scratch + dent