

INSPECTION REPORT

End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 308615 |
| License plate | 2BMM287 |
| Vehicle identification number | KMHC851CGNU280529 |
| Dossier | 2021 259 003 |
| Make | Hyundai Ioniq 1.6GDi Hybride F |
| Mileage | 130994 |
| First registration | 14/01/2022 |
| client availability date | 19/03/2026 |
| inspectionDate | 24/03/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|---|------------|
| 11 | Bumper Front // Smart Repair Medium | N |
| 18 | Bumper Front / Spoiler / Replace | Y |
| 92 | Rocker Panel Left // Painting | Y |
| 108 | Door Rear Left / Door Handle / Replace | N |
| 134 | Bumper Rear // Repair & Painting | N |
| 184 | Wing Rear Right // Repair & Painting | N |
| 190 | Door Rear Right // Smart Repair Small | N |
| 202 | Rocker Panel Right // Painting | Y |
| 214 | Door Front Right // Repair & Painting | Y |
| 233 | Wing Front right // Painting | N |
| 311 | Wheel Alloy Front Left // Repair | N |
| 321 | Wheel Alloy Rear Left // Repair | N |
| 331 | Wheel Alloy Rear Right // Repair | N |
| 634 | Rear Left Door Interior Coating // Replace Completely | Y |

Damage Pictures



Damage within Renta-norm-stone chipping



Rear Left Door Interior Coating // Replace Completely-scratch



Wing Front right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Smart Repair Medium-scratch




Door Front Right // Repair & Painting-dent



Door Rear Right // Smart Repair Small-dent




Wing Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-bad repair



Door Rear Left / Door Handle / Replace-cracked



Rocker Panel Right // Painting-rust



Rocker Panel Left // Painting-rust