

INSPECTION REPORT


End of contract


GENERAL INFO

File	320750
License plate	2CEW232
Vehicle identification number	TMBGH6NW0N3107188
Dossier	2021 328 171
Make	Skoda Kamiq 1.0TGI 66kW Monte
Mileage	41950
First registration	28/06/2022
client availability date	24/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	N
40	Windshield // Repair	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
153	Rear Bonnet // Painting	Y
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
311	Wheel Alloy Front Left // Repair	N
431	Seat Rear Left // Repair	Y
543	Interior // Ionization Odor	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet // Painting-scratch



Bumper Rear // Painting-scratch



Wing Rear Left // Painting-scratch




Door Rear Left // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Rear Left // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Dashboard / Steering Wheel / Replace-scratch



Wing Rear Right // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-dent



Door Front Left // Repair & Painting-dent



Bumper Front / Spoiler / Replace-scratch + dent





Windshield // Repair-cracked



Roof // Polish-Chemical reaction



Rear Bonnet // Polish-Chemical reaction



Front Bonnet // Painting-Chemical reaction



Interior Cleaning // Small-dirty