

INSPECTION REPORT

End of contract

GENERAL INFO

File	316274
License plate	1XNS467
Vehicle identification number	W1K1771031J206345
Dossier	2019276006
Make	Mercedes A Berline 180 d Bus.S
Mileage	61819
First registration	21/02/2020
client availability date	10/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
135	Bumper Rear // Replace & Painting	N
146	Back Side / Reflector L / Replace	N
13	Bumper Front // Painting	N
234	Wing Front right // Repair & Painting	N
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
18	Bumper Front / Spoiler / Replace	Y
32	Front Bonnet // Painting	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
208	Rocker Panel Right / Cover Not Painted / Replace	Y
214	Door Front Right // Repair & Painting	N
225	Side View Mirror Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
432	Seat Rear Left / Bottom Coating / Replace	N
543	Interior // Ionization Odor	Y
544	Interior / Floor Covering / Replace	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-bad position



Side View Mirror Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Front Bonnet // Painting-scratch



Rocker Panel Right / Cover Not Painted / Replace-dent



Bumper Front / Spoiler / Replace-dent



Roof // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch




Door Rear Left // Painting-scratch




Wheel Two Tone Rear Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent




Wing Rear Right // Repair & Painting-scratch + dent





Door Rear Right // Repair & Painting-scratch + dent




Door Front Right // Repair & Painting-scratch + dent



Seat Rear Left / Bottom Coating / Replace-Incinerated




Interior / Floor Covering / Replace-Incinerated



Seat Front Left / Bottom Coating / Replace-Incinerated



Back Side / Reflector L / Replace-cracked



Bumper Rear // Replace & Painting-cracked



Wing Front right // Repair & Painting-scratch + dent



Bumper Front // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Tyre Rear Right // Replace-tear