

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309215
License plate	2ABA953
Vehicle identification number	TMBJJ7NX3MY109706
Dossier	2020 328 081
Make	Skoda Oct.Com.2.0TDI 110kW Sty
Mileage	176502
First registration	04/02/2021
client availability date	30/03/2026
inspectionDate	02/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
13	Bumper Front // Painting	Y
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
156	Rear Bonnet // Polish	Y
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
619	Front Left Door Interior Coating / Control Module / Replace	N

## Damage Pictures



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Front Left Door Interior Coating / Control Module / Replace-cracked



Front Bonnet // Polish-Chemical reaction




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Bumper Front // Painting-scratch




Wheel Alloy Front Right // Repair-scratch



Door Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



See External Expertise-dent