

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	311333
License plate	2BGE044
Vehicle identification number	VF3MCYHZMMS221916
Dossier	2021085009
Make	Peugeot 3008 1.5BHDi 96kW Allu
Mileage	146136
First registration	12/11/2021
client availability date	28/04/2026
inspectionDate	06/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	Y
13	Bumper Front // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
161	Roof // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	N
202	Rocker Panel Right // Painting	Y
213	Door Front Right // Painting	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Right // Painting-scratch



Door Front Right // Painting-scratch



Bumper Rear // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Smart Repair Medium-scratch



Bumper Front // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Roof // Smart Repair Medium-scratch + dent



Door Rear Right // Repair & Painting-bad repair