

INSPECTION REPORT



End of contract

GENERAL INFO

File	306687
License plate	1YVR863
Vehicle identification number	W1N2533111F908768
Dossier	2020 274 027
Make	Mercedes GLC Coupé 300de 4M
Mileage	92404
First registration	05/01/2021
client availability date	04/03/2026
inspectionDate	09/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
116	Wing Rear Left // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
340	Wheel Two Tone Front Right // Repair	N
421	Seat Front Right // Repair	N

Damage Pictures





Damage within Renta-norm-



Side View Mirror Left / Direction Indicator / Replace-scratch



Wing Rear Left // Polish-scratch



Seat Front Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent



Front Bonnet // Painting-scratch + dent



Side View Mirror Right / Direction Indicator / Replace-cracked