

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306856
License plate	1XQM882
Vehicle identification number	W1V4156031U281136
Dossier	2019331183
Make	Mercedes Citan 109CDI L2 Perf.
Mileage	95266
First registration	09/03/2020
client availability date	27/02/2026
inspectionDate	09/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	N
54	Headlight / Front left / Replace	Y
112	Wing Rear Left // Smart Repair Large	N
162	Roof // Painting	N
191	Door Rear Right // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	N
244	Light / Front Right / Replace	N
303	Rear Loading Door Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N
599	Trunk Lid Interior Coating / MDF Side Door Right / Replace	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N
883	Key Price Range 2 //	N

## Damage Pictures






Damage within Renta-norm-scratch



Wheel Alloy Front Left // Repair-scratch



Rear Loading Door Right // Painting-scratch




Door Rear Right // Repair & Painting-dent




Door Rear Right // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Large-scratch + dent



Key Price Range 2 //-cracked



Trunk Lid Interior Coating / MDF Rear Right / Replace-cracked



Trunk Lid Interior Coating / MDF Rear Left / Replace-cracked




Light / Front Right / Replace-cracked




Trunk Lid Interior Coating / MDF Side Door Right / Replace-cracked



Seat Front Left / Bottom Coating / Replace-Incinerated



Windshield // Replace-glass damage



Roof // Painting-Chemical reaction



Interior Cleaning // Small-stain



Headlight / Front left / Replace-N comf / out of order



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch