

INSPECTION REPORT


End of contract

GENERAL INFO

File	306645
License plate	2BRT164
Vehicle identification number	VF3VFEHS7NZ007032
Dossier	2021258079
Make	Peugeot Exp.Lo.2.0BHDi 145 L3
Mileage	163951
First registration	28/02/2022
client availability date	24/02/2026
inspectionDate	10/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
17	Bumper Front // Replace without painting	N
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
117	Wing Rear Left / Trim / Replace	N
137	Bumper Rear // Replace without painting	Y
161	Roof // Smart Repair Medium	Y
163	Roof // Repair & Painting	N
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
234	Wing Front right // Repair & Painting	N
294	Rear Loading Door Left // Repair & Painting	Y
304	Rear Loading Door Right // Repair & Painting	Y
540	Interior // Repair 1	Y
557	Central Console / Handbrake / Replace	Y
561	Dashboard // Repair	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	N
618	Front Left Door Interior Coating / Door Handle / Replace	Y

Damage Pictures



Damage within Renta-norm-



Rocker Panel Left // Smart Repair Medium-scratch



Front Left Door Interior Coating / Door Handle / Replace-scratch







Wing Front right // Repair & Painting-dent




Roof // Repair & Painting-dent



Interior // Repair 1-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Trunk Lid Interior Coating / MDF Rear Left / Replace-cracked



Roof // Smart Repair Medium-stone chipping



Central Console / Handbrake / Replace-scratch



Dashboard // Repair-scratch



Door Front Right // Polish-scratch




Door Rear Right // Polish-scratch



Door Rear Right / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Replace without painting-scratch



Wing Rear Left / Trim / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Bumper Front // Replace without painting-scratch



Bumper Front // Smart Repair Large-scratch