

INSPECTION REPORT

End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 306979 |
| License plate | 2ACD238 |
| Vehicle identification number | TMBJG7NX6MY108080 |
| Dossier | 2020286004 |
| Make | Skoda Oct.Com.2.0TDI 85kW Ambi |
| Mileage | 157335 |
| First registration | 16/02/2021 |
| client availability date | 03/03/2026 |
| inspectionDate | 10/03/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 3 | Y | |
| Spare wheel | | Y | |
| Towbar (+keys) | | Y | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | N | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|--|------------|
| 12 | Bumper Front // Smart Repair Large | N |
| 32 | Front Bonnet // Painting | Y |
| 124 | Light / Rear left / Replace | N |
| 149 | Back Side / Park Assist Sensor / Replace | N |
| 156 | Rear Bonnet // Polish | Y |
| 159 | Rear Bonnet / Rear Window / Replace | Y |
| 186 | Wing Rear Right // Polish | Y |
| 320 | Wheel Two Tone Rear Left // Repair | Y |

Damage Pictures





Damage within Renta-norm-



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Rear Bonnet // Polish-scratch




Wing Rear Right // Polish-scratch




Light / Rear left / Replace-cracked



Wheel Two Tone Rear Left // Repair-Chemical reaction



Front Bonnet // Painting-stone chipping



Back Side / Park Assist Sensor / Replace-Chipped paint