

INSPECTION REPORT

End of contract

GENERAL INFO

File	320892
License plate	2ATV828
Vehicle identification number	TMAJE812DNJ037555
Dossier	2021 070 140
Make	Hyundai Tuc.TGD ⁱ PHEV 195kW 4x
Mileage	111126
First registration	14/07/2021
client availability date	26/08/2026
inspectionDate	01/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
61	Wing Front Left // Smart Repair Medium	N
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
111	Wing Rear Left // Smart Repair Medium	N
130	Bumper Rear // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
193	Door Rear Right // Painting	N
210	Door Front Right // Smart Repair Small	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Smart Repair Small-scratch




Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch





Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Painting-scratch





Door Rear Left // Painting-scratch



Door Front Right // Smart Repair Small-dent



Roof // Smart Repair Medium-dent






Wing Rear Left // Smart Repair Medium-scratch + dent





Wing Front Left // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Right // Painting-bad repair



Wing Front right / Trim / Replace-worn