

INSPECTION REPORT


End of contract

GENERAL INFO

File	303731
License plate	2BEE527
Vehicle identification number	W1K1771101J334758
Dossier	2021090080
Make	Mercedes A Berline 180 d Bus.S
Mileage	94206
First registration	19/10/2021
client availability date	26/01/2026
inspectionDate	26/02/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
66	Wing Front Left // Polish	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
83	Door Front Left // Painting	Y
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
170	Roof / Full Panoramic Roof Medium / Replace	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	N
196	Door Rear Right // Polish	Y
211	Door Front Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	N
316	Tyre Front Left // Replace	Y
336	Tyre Rear Right // Replace	Y
346	Tyre Front Right // Replace	Y
412	Seat Front Left / Bottom Coating / Replace	N
540	Interior // Repair 1	Y
541	Interior // Repair 2	N
543	Interior // Ionization Odor	N
850	Certificate of Conformity //	Y
851	Registration Card loss Arval name //	Y
860	Interior Cleaning // Small	N


Damage Pictures



Damage within Renta-norm-



Light / Rear Right / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch




Wing Front Left // Polish-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch




Door Rear Left // Polish-scratch



Light / Rear left / Replace-scratch




Rear Bonnet // Polish-scratch



Roof / Full Panoramic Roof Medium / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Medium-scratch + dent



Wing Rear Left // Painting-bad repair



Door Front Left // Painting-bad repair



Windshield // Repair-cracked



Front Bonnet / Insulation / Replace-cracked



Seat Front Left / Bottom Coating / Replace-Incinerated



Interior // Repair 2-Incinerated



Interior // Repair 1-missing





Wing Rear Right // Painting-Chemical reaction




Roof // Polish-Chemical reaction



Door Rear Right // Polish-Chemical reaction



Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Small-stain



Tyre Front Left // Replace-worn



Tyre Front Right // Replace-worn



Tyre Rear Right // Replace-hole