

INSPECTION REPORT


End of contract

GENERAL INFO

File	314275
License plate	2HJH377
Vehicle identification number	TMAH151B1SJ252113
Dossier	2025195062
Make	Hyundai i30 1.0T-GDI 73kW Twis
Mileage	17067
First registration	29/07/2025
client availability date	09/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
81	Door Front Left // Smart Repair Medium	Y
92	Rocker Panel Left // Painting	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
208	Rocker Panel Right / Cover Not Painted / Replace	Y
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
340	Wheel Two Tone Front Right // Repair	Y
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N


Damage Pictures



Wheel Two Tone Front Right // Repair-scratch





Bumper Front / Trim Right / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Rocker Panel Left // Painting-scratch



Door Rear Left // Polish-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Polish-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch






Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch



Interior // Repair 1-Incinerated



Interior Cleaning // Small-stain



Rocker Panel Right / Cover Not Painted / Replace-bad position