

INSPECTION REPORT


End of contract

GENERAL INFO

File	304070
License plate	1XGG879
Vehicle identification number	WDB9066331P635450
Dossier	2019 255 072
Make	Mercedes Spr.314CDi A2H2 3.5T
Mileage	139170
First registration	23/12/2019
client availability date	20/02/2026
inspectionDate	16/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
17	Bumper Front // Replace without painting	N
50	Headlight / Front left / Repair	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	N
137	Bumper Rear // Replace without painting	N
174	Light / Rear Right / Replace	N
183	Wing Rear Right // Painting	N
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
234	Wing Front right // Repair & Painting	Y
240	Headlight / Front Right/ Repair	Y
294	Rear Loading Door Left // Repair & Painting	Y
304	Rear Loading Door Right // Repair & Painting	N
313	Wheel Steel Front Left // Replace	Y
323	Wheel Steel Rear Left // Replace	Y
333	Wheel Steel Rear Right // Replace	Y
860	Interior Cleaning // Small	Y
880	Emergency Key //	N

Damage Pictures






Damage within Renta-norm-



Side View Mirror Left / Direction Indicator / Replace-scratch



Headlight / Front left / Repair-scratch




Headlight / Front Right/ Repair-scratch



Wing Rear Right // Painting-scratch



Rear Loading Door Left // Repair & Painting-dent



Wing Front right // Repair & Painting-scratch + dent




Bumper Front // Replace without painting-scratch + dent




Door Front Right // Repair & Painting-scratch + dent




Door Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Replace without painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Light / Rear Right / Replace-cracked



Rear Loading Door Right // Repair & Painting-cracked



Light / Rear left / Replace-cracked



Side View Mirror Right / Direction Indicator / Replace-cracked




Emergency Key //-missing




Wheel Steel Rear Left // Replace-rust



Wheel Steel Front Left // Replace-rust



Wheel Steel Rear Right // Replace-rust



Interior Cleaning // Small-stain