

INSPECTION REPORT



End of contract

GENERAL INFO

File	321770
License plate	LW9983
Vehicle identification number	TMBJR0NX7NY103912
Dossier	2021063034
Make	Skoda Octav.Comb 1.5eTec 150 S
Mileage	153412
First registration	09/06/2022
client availability date	08/09/2026
inspectionDate	10/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
13	Bumper Front // Painting	Y
80	Door Front Left // Smart Repair Small	Y
93	Rocker Panel Left // Repair & Painting	N
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
219	Door Front Right / Window / Replace	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
641	Rear Right Door Interior Coating // Repair	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Rocker Panel Right // Smart Repair Medium-dent



Interior // Repair 1-Incinerated




Rocker Panel Left // Repair & Painting-rust




Interior Cleaning // Small-stain



Bumper Rear // Painting-scratch




Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right / Window / Replace-scratch



Wing Front right // Polish-scratch



Bumper Front // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wing Rear Left // Polish-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch





See External Expertise-dent