

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306688
License plate	2AAF024
Vehicle identification number	W1N2533111F915279
Dossier	2020 279 061
Make	Mercedes GLC Coupé 300de 4M
Mileage	72498
First registration	29/01/2021
client availability date	04/03/2026
inspectionDate	05/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
213	Door Front Right // Painting	N

## Damage Pictures




Damage within Renta-norm-




Bumper Front // Smart Repair Large-scratch




Rocker Panel Left // Smart Repair Medium-dent



Door Front Left // Painting-scratch + dent



Door Front Right // Painting-scratch + dent



Bumper Rear // Painting-bad repair